

Case Study: Difficult to Mitigate Home

Matt Koch

AVIP 2025 Conference





Now part of



FULLTERRA



Geo**Kinetics**
A FULLTERRA COMPANY



What Makes a Structure Difficult to Mitigate?

- Area work can be done is limited
 - Construction details
 - Limited or no access to areas
 - Finishes
- Poor communication/pressure field extension (PFE)
- Work done – you think you have PFE – levels are still high
 - It doesn't make sense
 - It always makes sense; you need to figure out why
- Source not easily identifiable
 - Water
 - Building materials
 - Soil
 - You missed something



Case Study House

- Mid-Century Modern House in Georgia
 - Three foundation types: slab on grade, basement, and crawlspace
 - Radon levels 10 pCi/L+/-

7.5 pCi/L
Master (first floor)

11.8 pCi/L
Crawlspace
(under master)




8.5 pCi/L
Basement



10.8 pCi/L
Main living area


Case Study House

- Mid-Century Modern House in Georgia
 - Person living in the house has lung cancer
 - There are three active mitigation systems in the home!
 - What was missed?




Why Do the High Radon Levels Make Sense?

- Clean Vapor called in to investigate
- Diagnostic testing performed



Why Do the High Radon Levels Make Sense?

- Performance of each system measured
 - Air flow in exhaust vent
 - Air pressure across fan
 - Sub-slab PFE
 - Sub-membrane PFE



Why Do the High Radon Levels Make Sense?

- Performance of each system measured
 - Air flow in exhaust vent
 - Air pressure across fan
 - Sub-slab PFE
 - Sub-membrane PFE

Existing Blower	Vacuum ("w.c.)	Airflow (CFM)
SP-1 - AMG Eagle	-1.16	207
SP-2 - AMG Eagle Supreme	-3.94	16
SP-3 - AMG Fury	-1.17	155


Test Hole	Distance (ft.)	Baseline
FT-1	57	-0.0015
FT-2	31	-0.0285
FT-3	11	-0.0870

Test Hole	Distance (ft.)	Baseline
SP-2		
FT-4	6	-0.1575
FT-5	11	-0.0040
FT-6	11	N/A
FT-7	27	-0.0015

Test Hole	Distance (ft.)	Baseline
SP-3		
FT-8	5	-0.0094
FT-9	15	-0.0034
FT-10	10	N/A
FT-11	18	-0.0080
FT-12	24	-0.0017
FT-13	32	N/A
FT-14	42	-0.0048
FT-15	44	-0.0004
WT-16	51	-0.0004

What Do We Do to Fix This?

- Information evaluated
- Where are we not getting sufficient PFE?
- Plan for further work developed



What is the Plan?

- System 1: Slab on grade
 - Replace fan with high flow fan
 - Replace 3" pipe with 4" pipe
- System 2: Basement
 - Additional suction point
 - Higher pressure fan
- System 3: Crawlspace
 - Modify configuration to get better air flow across the space
- System 4: Crawlspace
 - Add another system at other end of crawlspace to get better PFE

Mobilization

System 1

- Intrusive evaluation of system
 - Cut pipe – inspect pipe
 - Good pit
 - 4” gravel
- Replace high pressure fan with high flow fan
- Replace 3” pipe with 4” pipe
- Air flow increases 25%



Mobilization

System 2

- Intrusive evaluation of system
 - Cut pipe – inspect pit
 - No pit dug
 - Hard Clay
- Dig larger pit
- Core hole in new concrete where trench for plumbing work was created to connect pit with loose soil under new concrete
- Replace fan with high pressure/high flow fan



Mobilization

System 3

- Intrusive evaluation of system
 - Cut vapor barrier – inspect vapor collection system
 - Tarps installed over soil
 - Perforated pipe installed ON TOP of tarps
 - Previously installed pipes to other side of crawlspace were abandoned
 - Area in center of crawlspace with block wall with exposed soil in center



Mobilization


System 3

- Cut tarp, install vapor barrier over top of vent pipe and seal to tarp on both sides
- Reinstall vapor barrier
- Tie into abandoned radon system pipes to provide suction points around perimeter of crawlspace
- Install vapor barrier in area with exposed soil and add depressurization point underneath



Mobilization


System 3



Work Performed


System 4

- New system installed at end of crawlspace
- Hole cored through block wall at end of hallway to provide suction point under slab
- 3" subsidence under slab
- Tie into pipe loop at end of crawlspace closest to basement area



Work Performed

System 4




Work Performed

- Where are we getting PFE now?
- What are the radon levels?

1.0 pCi/L
Master (first floor)
86% Reduction

0.9 pCi/L
Basement
84% Reduction



0.6 pCi/L
Main living area
94% Reduction

Takeaway

- Every structure can be mitigated
- If you do work and the radon levels do not go down, there is a source that has not been identified
- Mitigation is not just installing a pipe and fan, turn it on.... presto – low radon levels
- It is all about PFE
- IF YOU DO NOT KNOW YOUR PFE, YOU DON'T KNOW JACK!

Any Questions?

To discuss these findings, please contact Matt Koch, at mkoch@cleanvapor.com



Thank you!

